

Filing Receipt

Received - 2022-01-13 03:19:51 PM Control Number - 52667 ItemNumber - 41

PUBLIC UTILTY COMMISSION of TEXAS PROJECT NO. 52667

REPORT FOR WOOD COUNTY ELECTRIC COOPERATIVE, INC.

To comply with HB 4150, not later than January 14, 2022, each electric utility, municipally owned utility, or electric cooperative meeting the requirements of Section 6 of HB 4150 must file in Project No. 52667 a report with the following information:

A declaration that each distribution line above 1 kilovolt or transmission line above 60 kilovolts owned by the utility that crosses a lake listed in PURA § 38.004(b) meets the applicable vertical clearance requirements established in Rule 232 of the NESC Standard ANSI (c)(2).

- •The date on which the company verified each line's compliance with the applicable NESC Standard.
- For each utility that self-identified a line that did not meet vertical clearance requirements in an annual report filed in either Project 50596 or Project 51890, a declaration that each line identified in the annual report meets the NESC Standard.
- If a line over a lake listed in PURA § 38.004(b) does not meet the NESC Standard:
- o The name of line;
- o The name of lake and the county or counties in which the lake is located;
- o A narrative description of actions the utility will take to bring the line into

compliance with the NESC Standard; and o The date by when the line will be brought into compliance.

Within Wood County Electric Cooperative's service territory there are 7 lakes listed in PURA § 38.004: Bob Sandlin, Lake Cyprus Springs, Lake Fork, Lake Hawkins, Lake Holbrook, Lake Quitman, and Lake Winnsboro. Forty lake crossings were identified. Wood County Electric Cooperative, Inc. employed the services of POWER Engineers, out of Ft. Worth, Texas to survey, assess and make recommendations for any discrepancies.

WCEC did not report an instance of noncompliance in its Filings for either Project 50596 or Project 51890.

The following is a list of the crossings that were found to be in compliance with Rule 232 in effect September 1, 2019:

Line Section ID	Lake	County or Counties	Compliance Date
TRANSOH1400, Lake Fork Double Circuit Transmission Line.	Lake Fork	Hopkins, Rains and Wood	July 22, 2021
OH7339297002, Quitman Ckt Benton	Lake Fork	Hopkins, Rains and Wood	July 22, 2021
OH11334427002, Pleasant Grove Ckt Nichols	Lake Fork	Hopkins, Rains and Wood	July 22, 2021
TRANSOH1515, J.D. Nichols to E.O. Brown Transmission	Lake Fork	Hopkins, Rains and Wood	July 22, 2021

TRANSOH370, North Emory to Lake Fork Transmission	Lake Fork	Hopkins, Rains and Wood	July 22, 2021
OH216448, South Ckt Cathey	Lake Fork	Hopkins, Rains, and Wood	July 22, 2021
TRANSOH1400, Lake Fork Double Circuit Transmission Line.	Lake Fork	Hopkins, Rains and Wood	July 22, 2021
OH7339297002, Quitman Ckt Benton	Lake Fork	Hopkins, Rains and Wood	July 22, 2021
OH108209, Fellowship Ckt Crow	Lake Hawkins	Wood	July 22, 2021
OH73315277001, Holbrook Ckt Sand Springs	Lake Holbrook	Wood	July 22, 2021
OH103315414002_SEG2, Mineola Ckt Sand Springs	Lake Holbrook	Wood	July 22, 2021
OH7331546007, Holbrook Ckt Sand Springs	Lake Holbrook	Wood	July 22, 2021
OH553310125001, East Ckt Benton	Lake Quitman	Wood	July 22, 2021

The following is a list of the crossings that did not comply with Rule 232 in effect on September 1, 2019:

Line ID	Lake	Counties	Action	Est. Date	
				Compliance	
OH2348371001 East Ckt D.O. Aldridge	Bob Sandlin	Camp, Franklin and Titus	Replace 1 pole with taller poles.	Q4 2022	
OH25234741001, East Ckt Hill Wilson	Lake Cypress	Franklin	Reframe Pole.	Q1 2022	
OH2425, Mt. Vernon Ckt Merrill Carby	Lake Cypress	Franklin	Add in 1 new pole.	Q1 2022	
OH7339136005, North Ckt Cathey	Lake Fork	Hopkins, Rains and Wood	Replace 2 poles with taller poles.	Q4 2022	
OH7339136001, North Ckt Cathey	Lake Fork	Hopkins, Rains and Wood	Replace 7 poles with taller poles. This will require engineered foundations in the lake.	Q4 2022	
OH13339136001, North Ckt Cathey	Lake Fork	Hopkins, Rains and Wood	Replace 1 pole with a taller pole. Add in 2 new poles.	Q1 2022	
OH103839, North Ckt Cathey	Lake Fork	Hopkins, Rains and Wood	Replace 2 poles with taller poles.	Q1 2022	
OH7339188001, North Ckt Cathey	Lake Fork	Hopkins, Rains and Wood	Replace 2 poles with taller poles.	Q1 2022	

OH733349001, South Ckt E.O. Brown	Lake Fork	Hopkins, Rains and Wood	Replace 5 poles with taller Poles. This will require engineered foundations in the lake.	Q4 2022
OH73332100003, South Ckt EO Brown	Lake Fork	Hopkins, Rains and Wood	Replace 3 poles with taller poles. This will require engineered foundations in the lake.	Q4 2022
OH123352, North Ckt Cathey	Lake Fork	Hopkins, Rains and Wood	Replace 2 poles with taller poles.	Q1 2022
OH103945, North Ckt Cathey	Lake Fork	Hopkins, Rains and Wood	Add in 2 new poles.	Q1 2022
OH7333185006, High School Ckt J.G. Walker	Lake Fork	Hopkins, Rains and Wood	Replace 5 poles with taller Poles. This will require engineered foundations in the lake.	Q4 2022
OH7333184007, High School Ckt Walker	Lake Fork	Hopkins, Rains and Wood	Replace 4 poles with taller poles. This may require engineered foundations in the lake.	Q4 2022
OH733913007, North Ckt Cathey	Lake Fork	Hopkins, Rains and Wood	Replace 3 poles with taller poles and add in 2 new poles.	Q1 2022
OH108290, Fellowship Ckt Crow	Lake Hawkins	Wood	Replace conductor.	Q2 2022
OH443317378010, Fellowship Ckt Crow	Lake Hawkins	Wood	Replace 2 poles with taller poles.	Q2 2022
OH122495, Fellowship Ckt Crow	Lake Hawkins	Wood	Add in 2 new poles.	Q2 2022

OH4433173100003, Fellowship Ckt Crow	Lake Hawkins	Wood	Add in 1 new pole.	Q2 2022
OH103315426004_SEG4, Mineola Ckt Sand Springs	Lake Holbrook	Wood	Replace 2 poles with taller poles, and add in 1 new pole.	Q2 2022
OH103315424002-SEG5, Mineola Ckt Sand Springs	Lake Holbrook	Wood	Replace 2 poles with taller poles.	Q2 2022
OH105224_SEG2, Mineola Ckt Sand Springs	Lake Holbrook	Wood	Replace 2 poles with taller poles.	Q2 2022
oh543315294001, Mineola Ckt Sand Springs	Lake Holbrook	Wood	Replace 2 poles with taller poles.	Q2 2022
OH103315416010_SEG2, Mineola Ckt Sand Springs	Lake Holbrook	Wood	Replace 2 poles with taller poles.	Q2 2022
OH17830, Cartwright Ckt Weems	Lake Winnsboro	Wood	Replace 2 poles with taller poles and add 2 new poles.	Q2 2022
OH11334427002, Pleasant Grove Ckt Nichols	Lake Winnsboro	Wood	Add 2 new poles.	Q2 2022
OH19198, Sharon Ckt Weems	Lake Winnsboro	Wood	Replace 1 pole with a taller pole and add 1 new pole.	Q2 2022

AFFIDAVIT

I swear or affirm that I have personal knowledge of the facts stated in this report or am relying on people with personal knowledge, that I am competent to testify to them, and that I have the authority to submit this report on behalf of the affected entity. I further swear or affirm that all statements made in this report are true, correct, and complete.

Signature

Cliff H. Campbell

Assistant Manager/Chief Operating Officer

Wood County Electric Cooperative, Inc.

Sworn and subscribed before me this 12 day 14 mark , 2022

Month

Year

Notary Public in State of Texas

My commission expires on

AUGUST 10, 2024

